





FC-Accessories

Description	Part number	Drawing
Crimping sleeve for Ø 2.0 mm cable	CRHS-3500-2000	
Crimping sleeve for Ø 2.5 mm cable	CRHS-3500-2500	
Crimping sleeve for Ø 2.8 mm cable	CRHS-3500-2800	
Crimping sleeve for Ø 3.0 mm cable	CRHS-3500-3000	
Crimping sleeve for Ø 3.5 mm cable	CRHS-3500-3500	
Dust cap for connector	FRSK-2515-00x0	
Dust cap for adaptor	SSKO-0710-00x0	
Dust cap, undetachable for ferrule 2.5 mm	USKK-2500-00x0	
Dust cap, metal, for adaptor, screwable	SSKM-FCP0-8075	
Dust cap, metal, undetachable for connector, screwable	USKM-FCP0-8075	

Description	Part number	Drawing
Boots for cable, 33 mm long for Ø 2.0 mm cable	KBKN-0033-20XX	
Boots for cable, 33 mm long for Ø 2.5 mm cable	KBKN-0033-25XX	
Boots for cable, 40 mm long for Ø 2.8 mm up to 3.0 mm cable	KBKN-0040-30XX	
Boots for cable, 40 mm long for Ø 3.5 mm cable	KBKN-0040-35XX	
Boots for fiber, 25 mm long	KBKN-3525-09XX	

Die beiden letzten Stellen der Artikelnummer bitte mit dem Code für die gewünschte Farbe ergänzen.
Please replace XX with the code of desired colour.

XX =	Black = 10	Red = 20	Yellow = 30	Green = 40
	Blue = 50	Grey = 60	Orange = 70	White = 80